Inspection Report

Name of Work	:	Improvements to Drains and Concrete Roads in Thindlu Surrounding area in Ward No. 09, Vidyaranyapura Sub Division.
Work Order	:	EE/BTP/BBMP/KRIDL/WO/664/2013-14 Dated: 05.03.2014.
Agency	:	Technical Managar, KRIDL
B.R. No & Date	:	305/2014-15 Dated: 30.08.2014
Bill Amount	:	14,97,905.98
Job Code	:	009-14-000052
P. Code	:	P-1771
Date of Inspection	:	19-09-15

The above said Work Improvements to Drains and Concrete Roads in Thindlu Surrounding area in Ward-09 Vidyaranyapura has been Taken by the Concerned AE

The above said Work has been Inspected along with the Concerned AE

The Length of the C.C Road and Carriage Width of the Road at different chainages has been Verified and found Satisfactory.

The Work Done is Satisfactory

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Name of Work: Improvements to Drains and Concrete Roads in Thidlu Surrounding Area in *Ward No. 09 Vidyaranyapura Sub Division.*



Assistant Engineer
WardNo. 09

Verified

G.M.MUNIYAPPA
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photos Showing the Work of Improvements to Drains and Concrete Roads in Thindlu Surrounding area in Ward No. 09, Vidyaranyapura Sub Division.



Assistant Engineer
Ward No. 09

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photos Showing the Work of Improvements to Drains and Concrete Roads in Thindlu Surrounding area in Ward No. 09, Vidyaranyapura Sub Division.

Assistant Engineer
Ward No. 09

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photos Showing the Work of Improvements to Drains and Concrete Roads in Thindlu Surrounding area in Ward No. 09, Vidyaranyapura Sub Division.

Assistant Engineer
Ward No. 09

G.M.MUNIYAPPA,
B.E (ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photos Showing the Work of Improvements to Drains and Concrete Roads in Thindlu Surrounding area in Ward No. 09, Vidyaranyapura Sub Division.

Assistant Engineer
Ward No. 09

G.M.MUNIYAPPA,
B.E.(ELECT),B.E.(CIVIL)
EXECUTIVE ENGINEER(STD)
PUBLIC WORKS DEPARTMENT

Photos Showing the Work of Improvements to Drains and Concrete Roads in Thindlu Surrounding area in Ward No. 09, Vidyaranyapura Sub Division.

Assistant Engineer
Ward No. 09

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(R&D)
PUBLIC WORKS DEPARTMENT

Photos Showing the Work of Improvements to Drains and Concrete Roads in Thindlu Surrounding area in Ward No. 09, Vidyaranyapura Sub Division.



Assistant Engineer
Ward No. 09

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(BTD)
PUBLIC WORKS DEPARTMENT

Photos Showing the Work of Improvements to Drains and Concrete Roads in Thindlu Surrounding area in Ward No. 09, Vidyaranyapura Sub Division.





Assistant Engineer
Ward No. 09

G.M.MUNIYAPPA
B.E.(ELECT),D.E.(CIVIL)
EXECUTIVE ENGINEER(TH)
PUBLIC WORKS DEPARTMENT

Photos Showing the Work of Improvements to Drains and Concrete Roads in Thindlu Surrounding area in Ward No. 09, Vidyaranyapura Sub Division.

Assistant Engineer
Ward No. 09

G.M.MUNIYAPPA,
B.E.(ELECT) A.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photos Showing the Work of Improvements to Drains and Concrete Roads in Thindlu Surrounding area in Ward No. 09, Vidyaranyapura Sub Division.

Assistant Engineer
Ward No. 09

G.M.MUNIYAPPA,
B.E.(ELECT) B.E. (CIVIL)
EXECUTIVE ENGINEER(INTDY)
PUBLIC WORKS DEPARTMENT

Photos Showing the Work of Improvements to Drains and Concrete Roads in Thindlu Surrounding area in Ward No. 09, Vidyaranyapura Sub Division.

Assistant Engineer
Ward No. 09

G.M.MUNIYAPPA
B.E.(ELECT),D.E.(CIVIL)
EXECUTIVE ENGINEER(CIVIL)
PUBLIC WORKS DEPARTMENT

Photos Showing the Work of Improvements to Drains and Concrete Roads in Thindlu Surrounding area in Ward No. 09, Vidyaranyapura Sub Division.

Assistant Engineer
Ward No. 09

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT